Monday Afternoon Riverside, NJ March 12, 2018 Regular Meeting 4:35pm

STATEMENT:

Public Notice of this meeting pursuant to the Open Public Meetings Act has been given by the Riverside Sewerage Authority in the following manner:

- 1. Posting written notice on the official bulletin board at the Riverside Township Administrative Office Building on February 21, 2018.
- 2. Written notice was delivered to the Burlington County Times and the Courier Post on February 21, 2018.
- 3. Filed written notice with the Clerk of the Township of Riverside on February 21, 2018.

The regular meeting of the Riverside Sewerage Authority was held on the above date at the Riverside Township Municipal Building 1 W. Scott Street Riverside, NJ 08075.

ROLL CALL

Mr. Mingin – present, Mr. Horton – present, Mr. Conard – present, Mr. Van Meter – present, Mr. Haman – not in attendance.

Also present: Authority Secretary Susan M. Dydek, Treasurer Meghan Jack and Superintendent Joseph Bader.

RESOLUTIONS:

Mr. Conard made a motion to adopt Resolution 2018-#15 entitled, "<u>APPOINTMENT OF AN ACCOUNTANT</u>." seconded by Mr. Mingin. Upon roll call, the vote was as followed: Ayes – Messrs. Conard, Horton, Mingin and Van Meter. Nays – None. Motion carried.

Mr. Conard made a motion to adopt Resolution 2018-#16 entitled, "A RESOLUTION OF THE RIVERSIDE SEWERAGE AUTHORITY REMOVING THE APPEAL PROCEDURE FOR REDUCED RATES FOR NONCONSUMPTION OF WATER." seconded by Mr. Van Meter. Upon roll call, the vote was as followed: Ayes – Messrs. Conard, Horton, Mingin and Van Meter. Nays – None. Motion carried.

APPROVAL OF MINUTES:

Motion made by Mr. Conard and Mr. Van Meter that the minutes of the Reorganization Meeting of February 12, 2018 be approved as written carried.

Motion made by Mr. Van Meter and Mr. Conard that the minutes of the Work Session Meeting of February 12, 2018 be approved as written carried.

Motion made by Mr. Conard and Mr. Mingin that the minutes of the Regular Meeting of February 12, 2018 be approved as written carried.

RESOLUTION 2018 - #15

APPOINTMENT OF AN ACCOUNTANT

WHEREAS, there exists a need for an accountant, and

WHEREAS, funds are available for this purpose,

WHEREAS, in accordance with N.J.S.A. 19:44A-20.5, the Riverside Sewerage Authority, or any other agency or instrumentality thereof, shall not enter into a contract, including a professional service contract, having an anticipated value in excess of \$17,500, as determined by the municipality, agency or instrumentality, with a business entity, except a contract that is awarded pursuant to a fair and open process; and

WHEREAS, the Riverside Sewerage Authority publicly advertised in the Burlington County Times, the official newspaper, on February 8, 2018 the Request for Proposals / Request for Qualifications for Professional Services with the submission deadline of February 28, 2018 to submit such Request for Qualifications / Request for Proposals; and

WHEREAS, the Riverside Sewerage Authority has complied with the minimum requirements pursuant to N.J.S.A 19:44A-20.7.

NOW, THEREFORE, BE IT RESOLVED, by the Riverside Sewerage Authority as follows:

- 1. The Chairman and Secretary are hereby authorized and directed to execute the attached contract with Bowman and Company for a commencing on March 12, 2018 and ending on February 11, 2019. The hourly amount to be dispersed by the Riverside Sewerage Authority shall not exceed \$7,500.00 for accounting services, \$203.00 an hour for additional services and \$25,550.00 for Specialized Financial and Bonding Rates. The resolution and contract are on file and available for public inspection in the office of the Authority Secretary; and
 - 2. The firm will be required to comply with the requirements of P.L. 1975 C. 127.

Richard Horton, Vice - Chairman

ATTEST:

Susan M. Dydek, RMC

Authority Secretary

RESOLUTION 2018-#16

RESOLUTION OF THE RIVERSIDE SEWERAGE AUTHORITY REMOVING THE APPEAL PROCEDURE FOR REDUCED RATES FOR NONCONSUMPTION OF WATER

WHEREAS, the Riverside Sewerage Authority is a public body created by the Township of Riverside for the purpose of relieving waters in or bordering the State of New Jersey from pollution: and

WHEREAS, pursuant to N.J.S.A. 40:14A-1 et seq.., the "Sewerage Authority Law", the Riverside Sewerage Authority is authorized to charge and collect rates, referred to as "service charges," from occupants or owners of property for direct or indirect connection with or use or service of its sewerage collection and treatment system: and

WHEREAS, the Riverside Sewerage Authority deems service charges based upon water consumption to be the most practicable and equitable method of assessing sewer charges as it assures a uniform rate structure thereby providing a satisfactory revenue flow which will enable the Riverside Sewerage Authority to fulfill its environmental obligations; and

WHEREAS, the Riverside Sewerage Authority has determined that Resolution No.1999-22 is in need of revision to assure that there are sufficient revenues to pay all expenses of operation and maintenance of the sewerage system.

WHEREAS, THEREFORE, BE IT IS RESOLVED by the Riverside Sewerage Authority of the Township of Riverside, as follows:

THAT ANY AND ALL PROCEDURES GRANTING AN APPEAL FOR THE REDUCED RATES FOR NONCONSUMPTION OF WATER BE REMOVED (Chapter 44-3, Resolution 2012-#33). IN THE EVENT OF ANY DISCREPENCIES REGARDING THE CALCULATION OF SEWER CHARGES, WATER CONSUMPTION SHALL BE USED TO DETERMINE THE APPROPRIATE AMOUNT OF FEES TO BE CHARGED.

BY ORDER OF THE RIVERSIDE SEWERAGE AUTHORITY.

Richard Horton

Vice-Chairman

ichal S. Horton

ATTEST:

Susan M. Dydek, RMC
Authority Secretary

PUBLIC PORTION – (TECHNICAL):

1) Mr. James V. Sweezy – New Connection at 104 4th Street – There was a discussion on the connection procedure. Motion made by Mr. Conard, seconded by Mr. Mingin to approve the request for a new connection at 104 4th Street carried.

In seeing no additional members of the public wishing to speak, motion made by Mr. Van Meter and Mr. Conard that Public Portion (Technical) be closed carried.

OLD BUSINESS:

1) Financial Disclosure Statements must be filed by April 30, 2018.

NEW BUSINESS:

- 1) Inspection Fees. Secretary Dydek Reported that the current fees for a renewal inspection and a disconnection inspection are different and requested that the fees for inspection be uniform. Motion made by Mr. Conard and Mr. Mingin that a resolution be prepared for the next meeting adjusting the inspection rates carried.
- 2) NJWEA 103rd Annual Conference and Exposition May 7, 2018 May 11, 2018.
- 3) Murphy Family February 12, 2018 (left message on voicemail 2-11-18 @ 9:00pm) Sewer problem.
- 4) Thomas O. Taylor Sunday February 25, 2018 (emailed Meghan Jack) Sewer backing into downstairs, plumber called, opened manhole and sewer was backed up to cover.
- 5) Bob Zinick Plumber February 26, 2018 102 W. Washington Cannot locate vent.

ACTION:

None.

CORRESPONDENCE:

- 1) Maley Givens SJM Riverside, LLC, Request for Connection Fee Credit.
- 2) John Jenkins Letter of Resignation effective March 9, 2018. Motion made by Messrs. Conard and Van Meter to accept the resignation of John Jenkins carried.
- 3) Burlington County Board of Chosen Freeholders Exploring the possibility of the Riverside Sewerage Authority accepting a portion of the County's wastewater for treatment at the Riverside Sewerage Authority Plant. After a brief discussion, motion made by Messrs. Conard and Mingin to deny the acceptance of the County's wastewater at the Riverside Sewerage Plant for treatment carried.

REPORTS:

PLANT:

Mr. Conard reported that the plant is running smoothly. Mr. Conard also reported on the problems with the plant receiving the laboratory results.

APPEALS:

Mr. Mingin had no report.

REVENUE AND FINANCE:

Mr. Haman was not in attendance.

STREETS:

Mr. Van Meter reported that everything is running smoothly. There was one street opening at 218A Madison Street.

INSPECTIONS:

Mr. Horton reported that there was one inspection at 218A Madison Street which was inspected by the Assistant Superintendent. The lateral renewal was done satisfactory.

SUPERINTENDENT'S REPORT:

Superintendent Bader reported that QC/Euofin was contact by phone and email regarding their Effluent Analysis results and they insisted that their results were accurate. The NJDEP Southern Enforcement Inspector for Riverside was notified of the multiple Permit violations with January's Laboratory sampling. On March 1, 2018 liquid Caustic Soda was added to the Secondary Clarifiers to meet the NJPDES for the Plant effluent. Two properties were reported to the NJDEP doe lateral vent overflows. The properties are: 19 Lafayette Street, NJDEP Case #180201200322 and 434 Bridgeboro Street, NJDEP Case #180205225418. The property owner of 323 Cleveland Avenue was notified by Certified Mail that a check valve is required to be installed on laterals if a washtub or washing machine is located in a basement. The issues with the SCADA System communication issues has not been resolved. M&N Associates completed the replacement of a damaged inlet valve for Grit Chamber #1.

Motion made by Mr. Van Meter, seconded by Mr. Conard to accept the Superintendent's Report carried.

The report is on file in the Authority Secretary's Office.

ENGINEER'S REPORT:

The Engineer's Report was submitted.

Motion made by Mr. Conard, seconded by Mr. Mingin to accept the Engineer's Report carried.

The report is on file in the Authority Secretary's Office.

RIVERSIDE SEWERAGE AUTHORITY PLANT OPERATOR'S REPORT AUTHORITY MEETING - March 12, 2018

1. The Plant Performance Summary for January, 2018 is attached for review. There were four violations during this report period, which are highlighted for your review. QC/Eurofin was contacted by phone and email questioning their Effluent Analysis results, but QC/Eurofin insisted their data was accurate.

The NJDEP Southern Enforcement Inspector for Riverside was notified of the multiple Permit violations with January's Laboratory sampling.

March 1, 2018 the addition of liquid Caustic Soda to the Secondary Clarifiers was implemented to meet the NJPDES for the Plants Effluent. The NJPDES effluent pH requirement is a 6 pH and the Plant at some point received a very low influent pH of 4 pH. This low pH has not only effected the effluent, but the Nitrification Tower bacteria growth, which also can affect the effluents pH. I'm confident with the addition of the Caustic Soda and the increase of recirculation to the Nitrification Tower, the tower will be operating as designed by March 3, 2018.

The NJDEP was notified of a Laboratory Error with a January BOD analyses for the Plant's Permit requirements. The NJDEP case # is 180205225418. A code=E will be entered for this result on the DMR Report. [The email is attached for review].

The Residuals [Sludge] Management Summary for January, 2018 is also attached for review. Dewatered sludge [75 yds] was removed by the Woolston Company for composting at the County facility. Sludge processing with the Belt Filter Press has increased due to the Primary Digester being out of service.

2. The Trouble Log Summary for February, 2018 is attached for review.

Two Properties were reported to the NJDEP for a lateral vent overflow this reporting period.

- a. 19 Lafayette Street. NJDEP Case #180201200322.
 - b. 434 Bridgeboro Street. NJDEP Case # 180205225418.

434 Bridgeboro Street was reported to the Burlington County Health Department and the NJDEP [Case # 180205225418] February 5, 2018. The Owner of the property was contacted by phone, when at that time they were informed to rectify. The property was inspected again February 10, 2018. The vent was not overflowing.

The manhole in front of 230 Cleveland Avenue overflowed approximately 30 gallons. The NJDEP case # is 180214215539.

- 3. The Line Maintenance Summary for February, 2018 is attached for review.
- 4. The Activities Report for February/March 2018 is attached for review.
- 5. RSA once again received the Annual Safety Award from the JIF.

RIVERSIDE SEWERAGE AUTHORITY PLANT OPERATOR'S REPORT AUTHORITY MEETING - March 12, 2018

- 6. The Owner of 323 Cleveland Avenue was notified by Certified Mail February 15, 2018, that the Authority Bylaws requires a check valve be installed on laterals if a washtub or washing machine is installed in basement. The Return Receipt for the letter was received February 26, 2018. [A copy of the Letter is attached].
- 7. No measurements were recorded January/February 2018 for the Secondary Digester Dome tilt due to Safety Precautions.

[The Secondary Digester is not operating as designed. The Secondary Digester Dome requires methane gas produced in the Primary Digester for the secondary roof to float correctly. Until the repairs to the Primary Digester mixing system are made, the digester won't produce enough gas to lift the Secondary Digester Dome roof].

- 8. Sand Filter #3 has been returned to service. [The returned to service NJDEP case # is 180226155456]. The filter is operating as designed.
- 9. The SCADA communication issue with the Dialer still wasn't rectified by March 9, 2018. The Dialer will not recognize the alarms generated from the SCADA system. The RACO dialer is still under a five year warranty. A RACO representative will be contacted to assist Contech with the SCADA alarm integration.
- 10. The SED Utilization Report for January was submitted by email to the NJDEP for the Primary Digester Project. A notification of receipt was received.
- 11. Clyde Lattimer & Son Construction are currently in the process of construction on the Primary Digester Mixer Project. [The NJDEP out of service case #is 171206092456].
- 12. Pump #1 for Pump Station #2 in the Plant is generating a Seal Leak Alarm. The estimated cost to rebuild the pump was [\$5,000.00]. Three quotations for the pump rebuild repairs were requested from Willier Electric [\$4,915.00], Municipal Maintenance [\$5,810.00] and AC Schultes [\$11,083.00]. The quotation submittal period ended March 5, 2018. Willier Electric's quotation was accepted and they were requested for estimated start date.
- 13. Grit Chamber #1 [Out of service case # 170411125541] is still out of service as of March 9, 2018. There is an issue with the Drive Chain Gear. The wrong gear may have been sent, which a different gear will need to be sent.
- 14. M&N Associates has completed the replacement of the damaged Inlet Valve for Grit Chamber #1. M&N was onsite at 8:00 pm to start the repair of the valve and the repairs were completed at 3:45 am. The repairs required completion at a low flow time to prevent any backup into homes. [The NJDEP case #is 180301033644].

RIVERSIDE SEWERAGE AUTHORITY PLANT OPERATOR'S REPORT AUTHORITY MEETING - March 12, 2018

- 15. The Hooker Street Pump Station Confined Space Davit Project was completed by C. Stevenson & Son and Inspected by ERI. The Hooker Street Pump Station did not meet the PEOSH 29 CFR 1926.501 code. Unfortunately the Davit doesn't meet the 5,000 pounds of force per worker requirement for Fall Protection. ERI was contacted to submit an estimated cost to meet the OSHA Standard.
- 16. The conveyor parts required to rebuild Grit Conveyor #2 were received from Pyrz. Three quotations will be requested for the repairs when Grit Chamber #1 is returned to service.
- 17. The additional monthly data for the DRBC has been scheduled with QC/Eurofin to start April 2018 and to continue monthly until April 2020. No estimate for cost has been received. [The data is attached for review].

SUBMITTED BY

JOSEPH G. BADER SUPERINTENDENT

PLANT PERFORMANCE SUMMARY

January 2018

<u> </u>					Januar	7 2018
PARAMETER	PERMIT	REP	ORTED	PARAMETER	PERMIT	REPORTED
FLOW, EFFLUENT			eteni yeni	NITRATE (AS N), EFF	LUENT	1/6 months
Monthly Avg	Report	0.1	5 MGD	Mon Avg Conc	Report	Code = N MG/L
Daily Maximum	Report	0.32	MGD	Daily Max Conc	Report	Code = N MG/L
FLOW INFLUENT	排除多色有效。		海外性病	E.COLI		
Mon Avg Conc	Report	1.01	MGD	Monthly Geo Avg	126	76,681 /100N
Weekly Avg Conc	Report	2.67	MGD	Instant Max	Report	140.000 /100N
5 DAY BOD, INFLUEN		是其些是	25 以 多。	FECAL COLIFORM, E	FFLUENT	· 医多克尔斯氏
Mon Avg Conc	Report	234.67	MG/L	Monthly Avg	200/100ML	29.00 /100M
Weekly Avg Conc	Report	246.00	MG/L	Weekly Avg	400/100ML	29,00 /100M
5 DAY BOD, EFFLUEN	Toward Gard			BIOASSAY, EFFLUEN	Material Company	. 因数:000000000000000000000000000000000000
Mon Avg Loading	98 KG/D	40.45	KG/D	LC50,96 hr Acute	50%	Code = N %
Weekly Avg Loading	147 KG/D	83.35	KG/D	IC25 7 day Chronic	Report	Code = N %
Mon Avg Conc	30 MG/L	50.00	MG/L	CHLORINE PRODUC	ED OXIDANTS	EFFLUENT
Weekly Avg Conc	45 MG/L	88.80	MG/L	Mon Avg Conc	Report	0.010 MG/L
5 DAY BOD REMOVAL	EFFICIENCY	1=7 of 5 1		Daily Max Conc	Report	0.010 MG/L
Mon Avg Minimum	88.5%	79.21	%	TEMPERATURE, INFL	UENT	
pH:INFLUENT	利提及不够要 。	Factories by Els	双那些地	Minimum	Report	10.00 DEG 0
Minimum	Report	6.97	S.U.	Monthly Avg	Report	13,06 DEG C
Maximum	Report	7.95	S.U.	Maximum	Report	15.40 DEG C
pH, EFFLUENT		भव अध्या		TEMPERATURE, EFF	LUENT	
Minimum	6.00 S.U.	6.48	S.U.	Minimum	Report	6:60 DEG C
Maximum	9.00 S.U.	7.52	S.U.	Monthly Avg	Report	11.75 DEG C
TOTAL SUSP SOLIDS	INFLUENT	精制的		Maximum	Report	17.60 DEG C
Mon Avg Conc	Report	145,87	MG/L	DISSOLVED OXYGEN	EFFLUENT	
Weekly Avg Conc	Report	264.00	MG/L	Wkly Avg Conc [Min]	4.0 MG/L	6.00 MG/L
TOTAL SUSP SOLIDS,	EFFLUENT		4-22-6-25	PHOSPHOROUS, E	EFFLUENT	对。李多多家庭的
Mon Avg Loading	113 KG/D	72.31	KG/D	Mon Avg Conc	Report	5.20 MG/L
Weekly Avg Loading	170 KG/D	133.29	KG/D	Weekly Avg Conc	Report	5.20 MG/L
Mon Avg Conc	30 MG/L	88.30	MG/L	COPPER, EFFLUENT	新常星 医多级	《自然基础》是有特殊
Weekly Avg Conc.	45 MG/L	142.00	MG/L	Mon Avg Conc	Report	0.0532 MG/L
TOTAL SUSP SOLIDS R	EMOVAL EF	FICIENCY		Daily Max Conc	Report	0.0532 MG/L
Mon Avg Minimum	85.0%	3.00		ZINC EFFLUENT	内内外 乌海头	學是自然與問題
OIL&GREASE, EFFLUE	VT 建氯苯基	1/3month	S 💮	Mon Avg Conc	Report	0.1330 MG/L
Mon Avg Conc	10 MG/L	Code =N	MG/L	Daily Max Conc	Report	0,1330 MG/L
Daily Max Conc	15 MG/L	Code =N		Total Dissovled Solids	Effluent	1/month
AMMONIA NITROGEN (I	NOV-APR}, E	FFLUENT	在支持等	Mon Avg Conc	Report	Code≍E MG/L
Mon Avg Loading	75.7 KG/D	10.8420	KG/D	Daily Max Conc	Report	Code=E MG/L
Daily Max Loading	151.4 KG/D	12.2967	KG/D			
Mon Avg Conc	20 MG/L	14.8667	MG/L			
Daily Max Conc						

Code = N

Not Required This Monitoring Period

Code=E

Lab Error

LC50 96 hr Acute IC25 7 day Chronic

Required 1/6monthes
Required 1/ 12 Monthes

RESIDUALS MANAGEMENT SUMMARY

January 2017

THE THE PARTY OF T	D) TV (SEL) WE TO SE	RAW SLUDGE	Table 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
SLUDGE PRODUCE	- 14340 134000 13500 13500 1350		2.10 %
Total Gallons	108900.00 gal	% Total Solids, minimum	2.97 %
Average Gallons/Day	3512.90 gpd	% Total Solids, average	4.00 %
Total Dry Tons	0.00 dt	% Total Solids, maximum	82,14 %
Average Dry Tons/ Day	0.00 dt/d	% Total Volatile Solids, minimun)	
Total Metric Tons	0.00 mt	% Total Volatile Solids, average	85.04 %
Average Metric Tons/Day	0.00 mt/d	% Total Volatile Solids, maximum	90,47 %
	A	pH minimum	4.83 s.u.
LIQUID SLUDGE REMO		pH maximum	6,98 s.u.
Total Gallons	NA gal	sludge sample temperature, min	10.80 C
Average Gallons/Day	NA gpd	sludge sample temperature, avg	13.47 C
Total Dry Tons		sludge sample temperature, max	17.20 C
Average Dry Tons/ Day	NA dt/d		A Language of the second section of the
Total Metric Tons	NA mt	PRIMARY DIGESTER SLUE	
Average Metric Tons/Day	NA mt/d	% Total Solids, minimum	1.10 %
% Total Solids, Minimum	NA %	% Total Solids, average	1.55 %
% Total Solids, Average	NA %	% Total Solids, maximum	2.00 %
% Total Solids, Maximum	NA %	% Total Volatile Solids, minimum	75.00 %
pH, Minimum	NA s.u.	% Total Volatile Solids, average	75,68 %
pH, Maximum	NA s.u.	% Total Volatile Solids, maximum	76.36 %
		pH_minimum	0.00 s.u.
DEWATERED SLUDGE REA	//OVED	pH maximum	0.00 s.u.
Total Gallons to Belt Press	108900.00 gal	sludge sample temperature, min	0.00 C
Average Gallons/Day	3512.90 gpd	sludge sample temperature, avg	21.90 C
% Total Solids, minimum	18.60 %	sludge sample temperature, max	23.90 C
% Total Solids, average	19.20 %		
% Total Solids, maximum	19.80 %	SECONDARY DIGESTER SLU	
% Total Volatile Solids, minimum	81.72 %	% Total Solids, minimum	2.00 %
% Total Volatile Solids, average	83.29 %	% Total Solids, average	2,00 %
% Total Volatile Solids, maximum	84.85 %	% Total Solids, maximum	2,00 %
Total Wet Cubic Yards	75.00 wcy	% Total Volatile Solids, minimum	75.00 %
Average Cubic Yards/Day	2.42 wcuy/d	% Total Volatile Solids, average	75.00 %
Total Dry Metric Tons	10,35 dmt	% Total Volatile Solids, maximum	75.00 %
Average Dry Metric Tons a Day	0.33 dmt/d	pH minimum	6,53 s.u.
Total Metric Tons	NA mt	pH maximum	6,61 s.u.
Average Metric Tons/Day	NA mt/d	sludge sample temperature, min	19.20 C
		sludge sample temperature, avg	21.90 C
OPERATIONS	以此,所以 其中的	sludge sample temperature, max	23,90 C
Heat Exchange, Temp In, min	76.00 F		
Heat Exchange, Temp In, avg	83,10 F	VOLATILE SOLIDS REDUCTI	
Heat Exchange, Temp In, max	90.00 F	Raw to Secondary Digester, minimum	0.00 %
Heat Exchange, Temp Out, min	66.00 F	Raw to Secondary Digester, average	0.00 %
Heat Exchange, Temp Out, avg	75.06 F	Raw to Secondary Digester, maximum	0.00 %
Heat Exchange, Temp Out, max	88.00 F		
Detention Time, Primary Digester	34.16 days		
Detention Time, Secondary Digester	28.47 days		

N.R. = None Removed N.S. = Not Sampled N.W. = Not Working O.O.S. = Out Of Service R.T.S. = Return To Service N.I.S. = Not In Service

February 2018 Trouble Log Summary

2018-023 19 AFAYETTE STREET Manhole overflow Main clear Notified 2018-024 124 NORTH FAIRLEW STREET Fixture backup/overflow Lateral blocked Notified 2018-025 323 CLEVELAND AVENUE Backflow into property Main slow Flush/vac 2018-026 600 BLOCK FLIMORE STREET Line inspection Main slow Flush/vac 2018-027 500 BLOCK FLIMORE STREET Vent overflow Main slow Flush/vac 2018-029 434 BRIDGEBORO STREET Vent overflow Main clear Notified 2018-030 255 PROGRESS STREET Backflow into property Main clear Hush/vac 2018-030 255 PROGRESS STREET Backflow into property Main clear Hush/vac 2018-031 355 PROGRESS STREET Backflow into property Main clear Hush/vac 2018-032 418 BAUPHIN STREET Backflow into property Main clear Hush/vac 2018-033 5101-035 24 WESTRANUE Line inspection Main clear Hush/vac 2018-035 24 WEST WASHINGTON STREET Backflow into p	Date	Report #	Address	Condition(s) Reported		; ;
2018-023 19 LAFAVEITE STREET Manhole overflow Main clear 2018-024 124 NORTH FAIRVIEW STREET Fixture backup/overflow Lateral blocked 2018-025 323 CLEVELAND AVENUE Backflow into property Main slow 2018-027 500 BLOCK FILMORE STREET Line inspection Main slow 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-030 255 PROGRESS STREET Backflow into property Main clear 2018-031 418 DAUPHIN STREET Backflow into property Main slow 2018-032 SIXTH AND ARNDT AVENUE Line inspection Main slow 2018-033 SIXTH AND ARNDT AVENUE Manhole overflow Main slow 2018-035 230 CLEVELAND AVENUE Manhole overflow Main clear 2018-035 24 WEST HANCOCK STREET Machou into property Main clear 2018-036 24 WEST WASHINGTON STREET Locate Vent Main clear<		We said the	A Commence of the Commence of		Conumon(s) Found	Disposition
2018-024 124 NORTH FAIRVIEW STREET Fixture backup/overflow Lateral blocked 2018-025 323 CLEVELAND AVENUE Backflow into property Main slow 2018-026 600 BLOCK FILMORE STREET Line inspection Main slow 2018-028 434 BRIDGEBORO STREET Vent overflow Main clear 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-021 434 BRDGEBORO STREET Vent overflow Main clear 2018-031 418 DAULPHIN STREET Backflow into property Main clear 2018-032 57 KH AND ARNDT AVENUE Line inspection Main slow 2018-033 51XH ANCOCK STREET Manhole overflow Main clear 2018-035 24 WEST HANCOCK STREET Manhole overflow Main clear 2018-036 24 WEST WASHINGTON STREET Locate Vent Main clear 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear <td>1/2018</td> <td>2018-023</td> <td>19 LAFAYETTE STREET</td> <td>Manhole overflow</td> <td>Main clear</td> <td>Notified amountanes</td>	1/2018	2018-023	19 LAFAYETTE STREET	Manhole overflow	Main clear	Notified amountanes
2018-025 323 CLEVEIAND AVENUE Backflow into property Main slow 2018-026 600 BLOCK FILMORE STREET Line inspection Main slow 2018-027 500 BLOCK PLAWARE AVENUE Line inspection Main clear 2018-028 434 BRIDGEBORO STREET Vent overflow Main clear 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-030 255 PROGRESS STREET Backflow into property Main slow 2018-031 418 DAUPHIN STREET Backflow into property Main slow 2018-032 SIXTH AND ARNOT AVENUE Line inspection Main slow 2018-033 SIXTH AND ARNOT AVENUE Line inspection Main slow 2018-035 230 CLEVELAND AVENUE Mankout request Main clear 2018-036 24 WEST HANCOCK STREET Markout request Main clear 2018-037 400 SAINT MIHIEL DRIVE Backflow into property Main clear 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-040 CHESTER AVENUE Line inspection Main clear	2/2/2018	2018-024	124 NORTH FAIRVIEW STREET	Fixture backup/overflow	Lateral blocked	Notified owner/tennian
2018-026 GOD BLOCK FILMORE STREET Line inspection Main slow 2018-027 500 BLOCK DELAWARE AVENUE Line inspection Main slow 2018-028 434 BRIDGEBORO STREET Vent overflow Main clear 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-030 255 PROGRESS STREET Backflow into property Main slow 2018-031 418 DAUPHIN STREET Backflow into property Main slow 2018-032 418 DAUPHIN STREET Backflow into property Main slow 2018-033 SIXTH AND ARNOT AVENUE Line inspection Main slow 2018-034 CHESTER AVENUE Manhole overflow Main slow 2018-035 24 WEST HANCOCK STREET Markout request Main clear 2018-036 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-037 400 SAINT MIHIEL DRIVE Backflow into property Main clear 2018-039 102 WEST WASHINGTON STREET Line inspection Main clear 2018-040 CHESTER AVENUE Line inspection Main clear <	5/2018	2018-025	323 CLEVELAND AVENUE	Backflow into property	Main class	ואסתוופת סאוופו/רפנווומער
2018-027 500 BLOCK DELAWARE AVENUE Line inspection Main slow 2018-028 434 BRIDGEBORO STREET Vent overflow Main clear 2018-029 434 BRIDGEBORO STREET Vent overflow Main clear 2018-030 255 PROGRESS STREET Backflow into property Main slow 2018-031 418 DAUPHIN STREET Backflow into property Main slow 2018-032 148 DAUPHIN STREET Backflow into property Main slow 2018-033 SIXTH AND ARNDT AVENUE Line inspection Main slow 2018-034 CHESTER AVENUE Manhole overflow Main slow 2018-035 230 CLEVELAND AVENUE Manhole overflow Main clear 2018-035 24 WEST HANCOCK STREET Assist other Department Main clear 2018-036 417 DELAWARE AVENUE Backflow into property Main clear 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-040 CHESTER AVENUE Line inspection Main clear	2/5/2018	2018-026	600 BLOCK FILMORE STREET	Line inchestion	MOIO III	riush/vac/root cut sewer main
2018-028 434 BRIDGEBORO STREET Vent overflow Main clear 2018-029 434 BRIDGEBORO STREET Vent overflow Main clear 2018-030 255 PROGRESS STREET Backflow into property Main slow 2018-031 418 DAULPHIN STREET Backflow into property Main slow 2018-032 418 DAULPHIN STREET Backflow into property Main slow 2018-033 SIXTH AND ARNDT AVENUE Line inspection Main slow 2018-034 CHESTER AVENUE Manhole overflow Main slow 2018-035 24 WEST HANCOCK STREET Manhole overflow Main clear 2018-037 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-038 417 DELAWARE AVENUE Backflow into property Main clear 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-039 LOCATESTER AVENUE Line inspection Main slow 2018-039 LOCATESTER AVENUE Line inspection Main slow	2/5/2018	2018-027	500 BLOCK DELAWARE AVENUE	Tipe in spection	Main slow	Flush/vac/root cut sewer main
2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-029 434 BRDGEBORO STREET Vent overflow Main clear 2018-031 418 DAULPHIN STREET Backflow into property Main slow 2018-032 418 DAUPHIN STREET Backflow into property Main slow 2018-033 SIXTH AND ARNDT AVENUE Line inspection Main slow 2018-033 SIXTH AND ARNDT AVENUE Line inspection Main slow 2018-035 230 CLEVELAND AVENUE Manhole overflow Main slow 2018-035 24 WEST HANCOCK STREET Markout request Main clear 2018-037 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-038 417 DELAWARE AVENUE Locate Vent Main slow 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-040 CHESTER AVENUE Line inspection Main slow	2/5/2018	2018-028	434 BRIDGFRORD STREET		Main slow	Flush/vac/root cut sewer main
2018-031 255 PROGRESS STREET Backflow into property Main clear 2018-032 418 DAULPHIN STREET Backflow into property Main slow 2018-033 418 DAUPHIN STREET Backflow into property Main clear 2018-033 SIXTH AND ARNDT AVENUE Line inspection Main slow 2018-034 CHESTER AVENUE Line inspection Main slow 2018-035 230 CLEVELAND AVENUE Manhole overflow Main slow 2018-035 24 WEST HANCOCK STREET Markout request Main clear 2018-037 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-038 417 DELAWARE AVENUE Locate Vent Main slow 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-040 CHESTER AVENUE Line inspection Main slow	2/6/2018	2018-029	434 BRDGFBORO STREET	Vent overnow	Main clear	· Notified owner/tennant
2018-033 SIXTH AND ARNDT AVENUE Backflow into property Main slow 2018-033 SIXTH AND ARNDT AVENUE Line inspection Main slow 2018-034 CHESTER AVENUE Line inspection Main slow 2018-035 230 CLEVELAND AVENUE Manhole overflow Main slow 2018-035 24 WEST HANCOCK STREET Markout request Main clear 2018-037 400 SAINT MIHIEL DRIVE Backflow into property Main slow 2018-039 102 WEST WASHINGTON STREET Locate Vent Main slow 2018-039 102 WEST WASHINGTON STREET Line inspection Main slow 2018-040 CHESTER AVENUE Backflow into property Main slow 2018-040 CHESTER AVENUE Backflow into property Main slow 2018-040 CHESTER AVENUE Line inspection Main slow	11/2018	2018-030		Venic Overnow	Main clear	Notified Superintendent
2018-031418 DAULPHIN STREETBackflow into propertyMain slow2018-032418 DAUPHIN STREETBackflow into propertyMain clear2018-033SIXTH AND ARNDT AVENUELine inspectionMain slow2018-034CHESTER AVENUELine inspectionMain slow2018-035230 CLEVELAND AVENUEManhole overflowMain slow2018-03624 WEST HANCOCK STREETMarkout requestMain clear2018-037400 SAINT MIHIEL DRIVEAssist other DepartmentMain clear2018-03841Z DELAWARE AVENUEBackflow into propertyMain slow2018-039102 WEST WASHINGTON STREETLine inspectionMain slow2018-040CHESTER AVENUELine inspectionMain slow) } } } } }	233 PROGRESS SIREET	Backflow into property	Main slow	Flush/vac/root cut sewer main
2018-032418 DAUPHIN STREETBackflow into propertyMain clear2018-033SIXTH AND ARNDT AVENUELine inspectionMain slow2018-034CHESTER AVENUEUne inspectionMain slow2018-03524 WEST HANCOCK STREETMarkout requestMain clear2018-03624 WEST HANCOCK STREETMarkout requestMain clear2018-037400 SAINT MIHIEL DRIVEAssist other DepartmentMain clear2018-038417 DELAWARE AVENUEBackflow into propertyMain slow2018-039102 WEST WASHINGTON STREETLocate VentMain clear2018-040CHESTER AVENUELine inspectionMain slow	12/2018	2018-031	418 DAULPHIN STREET	Backflow into property	Main slow	Flish/vac/mot cut sewier main
2018-033 SIXTH AND ARNDT AVENUE Line inspection Main slow 2018-034 CHESTER AVENUE Inne inspection Main slow 2018-035 230 CLEVELAND AVENUE Manhole overflow Main clear 2018-036 24 WEST HANCOCK STREET Markout request Main clear 2018-037 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-038 417 DELAWARE AVENUE Backflow into property Main clear 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-040 CHESTER AVENUE Line inspection Main slow	13/2018	2018-032	418 DAUPHIN STREET	Backflow into property	Main clear	
2018-034 CHESTER AVENUE Line inspection Main slow 2018-035 230 CLEVELAND AVENUE Manhole overflow Main slow 2018-036 24 WEST HANCOCK STREET Markout request Main clear 2018-037 400 SAINT MHIEL DRIVE Assist other Department Main clear 2018-039 102 WEST WASHINGTON STREET Locate Vent Main slow 2018-040 CHESTER AVENUE Line inspection Main slow	2/14/2018	2018-033	SIXTH AND ARNDT AVENUE	Line inspection	M CC	October
2018-035 230 CLEVELAND AVENUE Manhole overflow Main slow 2018-036 24 WEST HANCOCK STREET Markout request 2018-037 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-039 102 WEST WASHINGTON STREET Locate Vent 2018-040 CHESTER AVENUE Line inspection Main slow Main slow Main slow Main slow Main slow Line inspection Main slow	2/14/2018	2018-034	CHESTER AVENUE	ion iocapacition	MOIS HIGH	riush/vac/root cut sewer main
2018-036 24 WEST HANCOCK STREET Markout request Main clear 2018-037 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-038 417 DELAWARE AVENUE Backflow into property Main slow 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-040 CHESTER AVENUE Line inspection Main slow	2/14/2018	2018-035	230 CLEVELAND AVENUE		Main slow	Flush/vac/root cut sewer main
2018-036 24 WEST HANCOCK STREET Markout request Main clear 2018-037 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-038 417 DELAWARE AVENUE Backflow into property Main slow 2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-040 CHESTER AVENUE Line inspection Main slow	0,700,70			Mannole overflow	Main slow	Flush/vac/root cut sewer main
2018-037 400 SAINT MIHIEL DRIVE Assist other Department Main clear 2018-038 41.7 DELAWARE AVENUE Backflow into property. Main slow 2018-039 102 WEST WASHINGTON STREET Locate Vent 2018-040 CHESTER AVENUE Line inspection Main slow	:o/ <018	2018-036	24 WEST HANCOCK STREET	Markout request	Main clear	Markout main/lateral/vent
2018-038 417 DELAWARE AVENUE Backflow into property. 2018-039 102 WEST WASHINGTON STREET Locate Vent 2018-040 CHESTER AVENUE Line inspection Main slow	20/2018	2018-037	400 SAINT MIHIEL DRIVE	Assist other Department	Main clear	Motified amondates
2018-039 102 WEST WASHINGTON STREET Locate Vent Main clear 2018-040 CHESTER AVENUE Line inspection Main slow	2/26/2018	2018-038	412 DELAWARE AVENUE	Backflow into property	Main close	ייסטויפת סאוופו/ הוווימונ
2018-040 CHESTER AVENUE Line inspection Main slow	2/26/2018	2018-039	102 WEST WASHINGTON STREET	Locate Vent	Majn clear	riusn/vac/root cut sewer main
	2/26/2018	2018-040	CHESTER AVENUE	Line inspection	Main slow	Flush/vac/root cut sewer main

February 2018 Line Maintenance Summary

Remarks	GRIT, GREASE	GRIT, GREASE, RAGS	GRIT, GREASE, RAGS	GREASE	GREASE, RAGS	GRIT & GREASE	GRIT GREASE	GRIT AND LIGHT GREASE	RAGS	RAGS	GREASE GRIT	GREASE & GRIT	GRIT
Distance	363	351	332	200	352	. 258	327	163	460	267	149	395	230
Diameter		&	£8	.	8	8	8	Ē	 	10"	₩.	∞	æ
Section	296-237	299-296	455-299	132-131	237-240	. 217-218	218-219	219-418	235-241	267-266	37-52	52-51	40-44
Location	Delaware Ave.	Delaware Ave.	Delaware Ave.	Filmore St.	Delaware Ave.	Progress St.	Progress St.	Progress St.	Arndt Ave.	Chester Ave. South	Lafayette St.	Lafayette St.	Jefferson St.
Report #	2018-0008	2018-0009	2018-0010	2018-0011	2018-0012	2018-0013	2018-0014	2018-0015	2018-0016	2018-0017	2018-0018	2018-0019	2018-0020
Date	2/1/2018	2/1/2018	2/1/2018	2/5/2018	2/5/2018	- 2/13/2018	2/13/2018	2/13/2018	2/14/2018	2/14/2018	2/21/2018	2/21/2018	2/21/2018

RIVERSIDE SEWERAGE AUTHORITY PO BOX 188 RIVERSIDE, NJ 08075

Office (856) 461-1460

Plant (856) 461-0700

Fax (856) 461-0428

ACTIVITIES REPORT February/March 2018

ABS Electric, Contech and Pennoni Associates were onsite for SCADA System Backup Training. Training was done in two groups.

Lattimer and Son Construction was onsite to start construction the Primary Digester Mixer Project.

Trouble Log Report Corrections on 323 Cleveland Avenue were made and emailed to all Authority Members and the Secretary for the Authority.

An Inspector for Pennoni Associates was onsite for the Primary Digester Mixer Project.

Collection Maintenance on Progress Street was performed.

The water in Sand Filter #3 was drained and the silica in the filter was leveled. The filter was filled with water again for a five day self-cleaning of the silica and then the filter can be returned to service.

Repairs to the Feed Water Line for the Building 6 Air Scrubber were performed. The water line broke due to freezing temperatures.

Additional information for the Pump Station 2 Pump rebuild was emailed to AC Schultes for their quotation.

The insulation for the Feed Water Line for the Building 6 Air Scrubber was replaced. The water line broke due to freezing temperatures.

Maintenance on the Transducers for the Effluent meter was performed. The meter is still not operating as designed. North East Technical was contacted to troubleshoot the issue.

Maintenance was performed on the Influent Pump Controller and the VFD for Raw Sewer Pump #3. The VFD is not operating as designed. Perfect Services was contacted to troubleshoot the issue.

Willier Electric was contacted to troubleshoot the Electrical Starters for Raw Sewer Pump #2. The starters may need replacement.

Primary Clarifier #2 was removed from service and draining started. An object fell into the clarifier and needs removal to prevent jamming of the Skimmer Arm.

The Annual Time Off Report for 2017 was emailed to the Authority's Treasurer.

North East Technical was contacted again to troubleshoot the Effluent Meter issue.

RIVERSIDE SEWERAGE AUTHORITY PO BOX 188 RIVERSIDE, NJ 08075

Office (856) 461-1460

Plant (856) 461-0700

Fax (856) 461-0428

Deltronics was onsite to complete the repairs to Grit Chamber #1. Repairs were not completed. There is an issue with the gear for the Grit Chain.

American Door and Window was onsite to repair the glass for a Building 1 Door. Repairs are complete.

The 6 hour composite sampling for February 21, 2018 was canceled due to a processing issue with the Plant.

Collection Maintenance on Lafayette Street was performed.

QC/Eurofin was contacted by phone and email questioning the Effluent Analysis results, but QC/Eurofin insisted their data was accurate.

The NJDEP Southern Enforcement Inspector was notified of the multiple Permit violations with January's Laboratory sampling.

Repairs were performed on the drain line for Clariflocculator #1. The out of service NJDEP case #is 180221193834. The returned to service NJDEP case # is 180222154001. The repairs are complete.

Jeff & John J. attended Rutgers for their first day of two day TCH training.

Sand Filter #3 has been returned to service. [The returned to service NJDEP case # is 180226155456]. The filter is operating as designed.

A faulty thermostat for the Building 6 heater was replaced. The heater is now operating as designed.

Repairs were performed on the Sludge Sampler for the Primary Clarifiers. Training on the sampler was conducted.

323 Cleveland Avenue was notified by Certified Mail the Authority Bylaws requires a check valve on laterals if a washtub or washing machine is installed in basement. The Return Receipt for the letter has been received.

M&N Associates were onsite to inspect the Valve replacement for Grit Chamber #1. The expected date of replacement is February 28, 2018.

Deltronics is onsite to continue repairs to Grit Chamber #1. Repairs are not complete.

The additional monthly data for the DRBC has been scheduled with QC/Eurofin to start April 2018 and to continue monthly until April 2020. No estimate for cost has been received.

RIVERSIDE SEWERAGE AUTHORITY PO BOX 188 RIVERSIDE, NJ 08075

Office (856) 461-1460

Plant (856) 461-0700

Fax (856) 461-0428

Joe B attended the JIF Annual Safety Incentive meeting in Toms River. RSA once again received the Annual Safety Award from the JIF.

Additional parts were purchased from Kennedy to replace the damaged valve for Grit Chamber #1. RSA picked up the parts.

Jeff & John J. attended Rutgers for their second day of two day TCH training.

M&N was onsite 8:00 pm to start the repair of the damaged Grit Chamber #1 valve. The repairs were completed at 3:45 am. The repairs needed to be completed at a low flow time to prevent any backup into homes, [The NJDEP case #is 180301033644].

A drum of Caustic Soda was purchased to adjust the Effluent pH to meet the NJPDES.

Maintenance was performed on the Caustic Pump before use.

The addition of Caustic Soda into the Secondary Clarifiers was started March 1, 2018.

The Analytical Standards for the RSA Laboratory Certification for NJDEP have be purchased from ERA.

John Jenkins ran the Belt Filter Press for 12 hours on Saturday March 3, 2018 to maintain safe sludge levels in the Plant's Treatment Process.

Received AC Schultes [\$11,083.00] quotation on the Pump Station 2 pump rebuild.

Perfect Services onsite to troubleshoot the VFD issues with RSP #3. The 4-20 ma module needs replacement.

Joe B attended a meeting at the Town Hall regarding Pennoni Bills.

RSA's acceptance of Willier Electric's quotation to rebuild Pump Station #2 pump was emailed March 7, 2018.

The October 2017 RTR for the Plant was reissued by email to the County.

Municipal Maintenance and AC Schultes were notified by email that RSA didn't accept their quotation's to rebuild Pump Station #2 pump.

All Licensed Plant Employees license numbers were submitted to the MEL for TCH Training purposes.

MONTHLY FINANCIAL REPORT:

Treasurer Jack reported that audit preparations are in the final stages and there will be a first quarter report submitted next month.

BILLS AND EXPENDITURES:

Motion made by Mr. Conard, seconded by Mr. Van Meter that all bills and expenditures be paid carried.

PUBLIC PORTION (INFORMATIONAL)

In seeing that no other members of the public were present, motion made by Mr. Conard and Mr. Van Meter that Public Portion (Informational) be closed, carried.

There being no further business to attend to, motion made by Mr. Conard and Mr. Van Meter the meeting be adjourned, and so declared by Vice-Chairman Horton.

Susan M. Dydek, RMC